

FIG. 1






FIG. 2




FIG. 3.






Fig. 4


[illegible][illegible]





FRONT

P16. 6







FIG. 8

RIGHT



BOTTOM FIG. 9




FIG. 10




FIG. 11c




FIG. 11b




FIG. 11a




FIG. 12




FIG. 13




Fig. 14.

© 2004 THE DRAWING AND THE DATA CONTAINED HEREIN ARE THE SOLE PROPERTY OF SENIOR OPERATIONS INC., FURNISHED FOR THE EXCLUSIVE USE OF PURCHASER, PURCHASER'S INSTALLER, AND/OR PURCHASER'S CUSTOMER. Duplicating or distributing drawings or data without the written permission of SENIOR OPERATIONS INC. is prohibited. SENIOR OPERATIONS INC. 2400 LONGVIEW INDUSTRIAL PARK NEW BRANFORD, CT 06350-1000 • (203) 339-6229 • FAX: (203) 339-4899 • (EMAIL) senior@senioroperations.com - (WWW) www.senioroperations.com